



8680-ML-RS-02 Rev A

Agency Model: 8680I

Table with 8 columns providing product documentation availability in various languages: English, French, German, Italian, Spanish, Chinese, Hebrew, and Turkish.

FCC Part 15 Subpart B Class B
This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions:
1. This device may not cause harmful interference.
2. This device must accept any interference received, including interference that may cause undesired operation.

Table with 8 columns providing cautionary information in various languages: English, French, German, Italian, Spanish, Chinese, Hebrew, and Turkish.

Para su uso en México, la operación de este equipo está sujeta a las siguientes dos condiciones:
1. Es posible que este equipo o dispositivo no cause interferencia perjudicial.
2. Este equipo o dispositivo debe aceptar cualquier interferencia, incluyendo la que pueda causar su operación no deseada.

Table with 2 columns: Canadian Compliance and Conformité à la réglementation canadienne. Details requirements for Canadian market entry.

Table with 2 columns: RF Radiation Exposure Statement and Déclaration d'exposition aux radiations RF. Provides information on radio frequency exposure limits.

RF Exposure
The equipment complies with FCC RF exposure limits set forth for an uncontrolled environment. The equipment must not be co-located or operating in conjunction with any other antenna or transmitter.

Table with 8 columns providing technical specifications and safety warnings in various languages: English, French, German, Italian, Spanish, Chinese, Hebrew, and Turkish.

Table with 8 columns providing technical specifications and safety warnings in various languages: English, French, German, Italian, Spanish, Chinese, Hebrew, and Turkish.

Table with 8 columns providing CE mark information and compliance details in various languages: English, French, German, Italian, Spanish, Chinese, Hebrew, and Turkish.

Table with 8 columns providing CE mark information and compliance details in various languages: English, French, German, Italian, Spanish, Chinese, Hebrew, and Turkish.

United Kingdom Contact: United Kingdom Honeywell Scanning and Mobility, Honeywell House, Skimped Hill Lane, Bracknell, Berkshire, RG12 1EB Phone: +44 (0)1344921052

Table with 8 columns providing safety warnings in various languages: English, French, German, Italian, Spanish, Chinese, Hebrew, and Turkish.

Table with 8 columns providing safety warnings in various languages: English, French, German, Italian, Spanish, Chinese, Hebrew, and Turkish.

Table with 8 columns providing safety warnings in various languages: English, French, German, Italian, Spanish, Chinese, Hebrew, and Turkish.

Table with 8 columns providing safety warnings in various languages: English, French, German, Italian, Spanish, Chinese, Hebrew, and Turkish.

Table with 8 columns providing safety warnings in various languages: English, French, German, Italian, Spanish, Chinese, Hebrew, and Turkish.

Table with 8 columns providing safety warnings in various languages: English, French, German, Italian, Spanish, Chinese, Hebrew, and Turkish.

Table with 8 columns providing safety warnings in various languages: English, French, German, Italian, Spanish, Chinese, Hebrew, and Turkish.

